



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
9321-48-0395
State Number
H1505

EQUIPMENT INSPECTED

State Number: H1505	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: SAVARIA	Speed: 25
Landings: 2	Installed: 03/22/2005	Rope Size:
Volts: 110	Complied: 03/22/2005	Entrances: 2
OWNER	OCCUPANT	
BLADEN CO SCHOOLS	WEST BLADEN HS PB #3	
PO BOX 2519	1600 NC HWY 410	
ELIZABETHTOWN, NC, 28337	BLADENBORO, NC, 28320	

INSPECTION INFORMATION

Inspection Date	Type Inspection	Certificate Status	Inspector	County
11/17/2009	Routine	Re-issued	48 - Martin	BLADEN

VIOLATIONS

8.6.4.7.1	Clean the elevator pit.
2.14.1.4.5	Put the in car stop switch in proper working order.

Items must be corrected by: 12/07/2009

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: CURLY Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

BLADEN CO SCHOOLS
PO BOX 2519
ELIZABETHTOWN, NC, 28337