

2.14.7.1.3

8.6.4.7.1

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9323-36-324
State Number 16045

		EQUIPMENT INSPECTED		
State Number: 16045	Type of Unit: Passenger		Floor to Floor: B to 2	
Capacity: 2100	Manuf: THYSSEN KRUPP		Speed: 100	
Landings: 3	Installed: 10/03/1995		Rope Size:	
Volts: 240	Complied: 10/03/1995		Entrances: 1	
OWNER			OCCUPANT	
ALAMANCE- BURLINGTON SCHOOL SYSTEM			WILLIAMS HIGH SCHOOL	
1712 VAUGHN RD			1307 S CHURCH ST	
BURLINGTON, NC, 27215			BURLINGTON, NC, 27215	
		INSPECTION INFORMATION		
Inspection Date 11/19/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
5.1.21.1 Put the	in car alarm bell in working orde	r.		

Items must be corrected by: 12/19/2009

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into complainace with current codes.

Violations pointed out to: office Inspector _____

To make changes to the invoice mailing address please call: 919-733-0372

THIS IS NOT AN INVOICE

ALAMANCE- BURLINGTON SCHOOL SYSTEM

An invoice will be mailed to: 1712 VAUGHN RD

Put the in car emergency light in working order. Hoistways and pits shall be kept free of dirt and rubbish.

BURLINGTON, NC, 27215