

## N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

## INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9323-36-5486 State Number 21423

1

	E	EQUIPMENT INSPECTED			
State Number: 21423	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: 1 to 2	
Capacity: 2500	Manuf: THYSSEN KRUPP		Speed: 75	Speed: 75	
Landings: 2	Installed: 01/21/2003		Rope Size: 0	Rope Size: 0	
Volts: 208	Complied: 01/21/2003		Entrances: 2	Entrances: 2	
OWNER		OCCUPANT			
ALAMANCE REALTY	ALAMANCE REALTY				
154 HUFFMAN MILL ROAD	154 HUFFMAN MILL ROAD				
BURLINGTON, NC, 27015		BURLINGTON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 11/19/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
110 Violations found					
Notify the Elevator Bureau in wri	ting on Corrected Violations Form v	when the following corrections	have been made in order to bri	ng your equipment into	
violations pointed out to: office					
	To make changes to the invoice ma				
THIS IS NOT AN	ALAMANCE REALTY				
INVOICE	An invoice will be mailed to:	154 HUFFMAN MILL F BURLINGTON, NC, 27			