



N C Department of Labor Elevator Bureau
1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
9323-48-3040
State Number
H1353

EQUIPMENT INSPECTED

State Number: H1353	Type of Unit: Hand Lift	Floor to Floor: 1 to 2
Capacity: 750	Manuf: GARAVENTA	Speed: 12
Landings: 2	Installed: 02/27/2003	Rope Size: 0
Volts: 120	Complied: 02/27/2003	Entrances: 2
OWNER	OCCUPANT	
VICTORIA RAG PATCH	VICTORIA RAG PATCH	
10164 BEACH DRIVE SW	10164 BEACH DRIVE SW	
CALABASH, NC, 28468	CALABASH, NC, 28468	

INSPECTION INFORMATION

Inspection Date 11/19/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

8.6.4.13.1[a] Properly maintain hoist way door interlocks or mechanical locks and electric contacts. 1ST. FL. DOOR LOCK NOT RELEASING.

Items must be corrected by: 12/09/2009

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: RANDY

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

VICTORIA RAG PATCH
10164 BEACH DRIVE SW
CALABASH, NC, 28468