

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9334-36-162
State Number 14573

1

	F	EQUIPMENT INSPECTED			
State Number: 14573	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: 1 to 3	
Capacity: 2000	Manuf: THYSSEN KRUPP		Speed: 100	Speed: 100	
Landings: 3	Installed: 07/07/1992		Rope Size:	Rope Size:	
Volts: 208	Complied: 07/17/1992		Entrances: 1		
OWNER	OCC	OCCUPANT			
ELON UNIVERSITY	ELON UNIV / CARLTON HALL				
PO BOX 2950	105 E HAGGARD AVE				
ELON, NC, 27244	ELC	ON, NC, 27244			
	INS	SPECTION INFORMATION			
Inspection Date 11/30/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
Notify the Elevator Bureau in was omplainace with current codes.	riting on Corrected Violations Form v	when the following corrections l	nave been made in order to bri	ng your equipment into	
Violations pointed out to: OFFICE					
	To make changes to the invoice ma				
THIS IS NOT AN	-	ELON UNIVERSITY			
INVOICE	An invoice will be mailed to:	PO BOX 2950 ELON, NC, 27244			