

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9336-36-4994
State Number 24655

1

	E	QUIPMENT INSPECTED			
State Number: 24655	Type of Unit: Passenger		Floor to Floor:	Floor to Floor: 1 to 2	
Capacity: 2100	Manuf: THYSSEN KRUPP		Speed: 100	Speed: 100	
Landings: 2	Installed: 04/19/2007		Rope Size: 0	_	
Volts: 208	Complied: 04/19/2007		Entrances: 1		
OWNER	OCCUPANT	OCCUPANT			
ELON UNIVERSITY	ELON ACADEMIC VILLAGE PAVILION				
NONE GIVEN	360 ANTIOCH RD				
ELON, NC, 00000	ELON, NC, 2	ELON, NC, 27215			
	INS	SPECTION INFORMATION			
Inspection Date 12/02/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
No violations found					
	riting on Corrected Violations Form v	when the following corrections ha	ave been made in order to bri	ng your equipment into	
omplainace with current codes	•		T		
/iolations pointed out to: bob					
	To make changes to the invoice ma	o make changes to the invoice mailing address please call: 919-733-0372			
THIS IS NOT AN		ELON UNIVERSITY			
INVOICE	An invoice will be mailed to:	NONE GIVEN ELON, NC, 00000			