

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9337-36-581
State Number 24497

1

	E	QUIPMENT INSPECTED		
State Number: 24497 Capacity: 2000 Landings: 3 Volts: 208	Type of Unit: Panal Manuf: OTIS Installed: 01/12 Complied: 01/12	/2007	Floor to Floor: 1 to 3 Speed: 125 Rope Size: Entrances: 1	
OWNER ELON UNIVERSITY CAMPUS BOX 2285 ELON, NC, 27244	OCCUP OAKS (204 NO	OCCUPANT OAKS @ ELON UNIVERSITY 204 NORTH WILLIAMSON DRIVE ELON, NC, 27244		
	INS	PECTION INFORMATION		
Inspection Date 12/03/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE
		VIOLATIONS		
Elevator Name: BUILDING	Fiting on Corrected Violations Form v	when the following corrections has	ave been made in order to brit	ng your equipment into
omplainace with current codes. Violations pointed out to: bob			Inspector	
THIS IS NOT AN INVOICE	To make changes to the invoice ma			