

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9338-36-1567
State Number 11748

1

	Е	QUIPMENT INSPECTED			
State Number: 11748	Type of Unit: Passenger			Floor to Floor: 1 to 2	
Capacity: 4000	Manuf: THYSSEN KRUPP		=	Speed: 125	
Landings: 2	Installed: 08/04/1987		Rope Size: Entrances: 1		
Volts: 208	Complied: 08/04/1987		Entrances: 1		
OWNER	OCCUI				
ELON UNIVERSITY PO BOX 2950	ELON UNIV / MODEL FINE ARTS 207 N WILLIAMSON AVE				
ELON, NC, 27244		NC, 27244			
	INS	SPECTION INFORMATION			
Inspection Date 12/04/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found					
otify the Elevator Bureau in wo	riting on Corrected Violations Form v	when the following corrections h	nave been made in order to bri	ng your equipment into	
iolations pointed out to: bob			Inspector		
	To make changes to the invoice mailing address please call: 919-733-0372				
THIS IS NOT AN INVOICE	An invoice will be mailed to:	ELON UNIVERSITY PO BOX 2950 ELON, NC, 27244			