



INSPECTION REPORT

IMPORTANT: Always use State Number in
any correspondence relating to your equipment
www.nclabor.com/elevator.htm
919-707-7927

Report Number
9349-48-5587
State Number
20696

EQUIPMENT INSPECTED

State Number: 20696	Type of Unit: Passenger	Floor to Floor: 1 to 3
Capacity: 2000	Manuf: CANTON	Speed: 100
Landings: 3	Installed: 07/22/2002	Rope Size: 0
Volts: 208	Complied: 07/24/1992	Entrances: 1
OWNER	OCCUPANT	
CLEAR WATER PLACE	CLEAR WATER PLACE	
1620 GOLEY HEWETT RD.	1620 GOLEY HEWETT RD.	
BOLIVIA, NC, 28422	BOLIVIA, NC, 28422	

INSPECTION INFORMATION

Inspection Date 12/15/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 48 - Martin	County BRUNSWICK
-------------------------------	----------------------------	---------------------------------	--------------------------	---------------------

10

VIOLATIONS

2.2.2.4 Put the sump pump in proper working order.

8.1.1[c] Keys shall be kept on the premises in a location readily accessible to the personnel in the assigned group, but not where they are accessible to the general public.

Items must be corrected by: 01/04/2010

Notify the Elevator Bureau in writing on Corrected Violations Form when the following corrections have been made in order to bring your equipment into compliance with current codes.

Violations pointed out to: Unavailable

Inspector _____

THIS IS NOT AN
INVOICE

To make changes to the invoice mailing address please call: 919-733-0372

An invoice will be mailed to:

CLEAR WATER PLACE
1620 GOLEY HEWETT RD.
BOLIVIA, NC, 28422