

N C Department of Labor Elevator Bureau 1101 Mail Service Center, Raleigh, NC 27699-1101

INSPECTION REPORT

IMPORTANT: Always use State Number in any correspondence relating to your equipment www.nclabor.com/elevator.htm 919-707-7927 Report Number 9365-36-0126
State Number 8879

1

	E	QUIPMENT INSPECTED			
State Number: 8879	Type of Unit: Pas	senger	Floor to Floor: 1 to 4		
Capacity: 2000	Manuf: SOUTHERN		Speed: 125	Speed: 125	
Landings: 4	Installed: 01/25/1978		Rope Size:		
Volts: 208	Complied: 02/03/	1978	Entrances: 2		
OWNER		OCCUPANT			
FRONT ST METHODIST CHURC	FRONT ST METHODIST CHURCH				
PO BOX 2597	136 S FISHER ST				
BURLINGTON, NC, 27216	BURLINGTON, NC, 27215				
	INS	SPECTION INFORMATION			
Inspection Date 12/31/2009	Type Inspection Routine	Certificate Status Re-issued	Inspector 36 - Kirkman	County ALAMANCE	
		VIOLATIONS			
No violations found	·····				
Tvo violations found					
otify the Elevator Bureau in writing	on Corrected Violations Form v	when the following corrections by	nave been made in order to bri	ng vour equipment into	
omplainace with current codes.	circula - foldions i offit v	ind folia i mig corrections i	and a star made in order to orr	6 Jour edurpment into	
iolations pointed out to: office					
То	make changes to the invoice ma				
THIS IS NOT AN INVOICE An	FRONT ST METHODIST CHURCH An invoice will be mailed to: PO BOX 2597 BURLINGTON NC 27216				